

Slip, trip and fall accident control

Slips and falls are a major cause of injury that occurs to both visitors and employees. The National Safety Council estimates that 25,000 slip and fall accidents occur daily in the USA. According to the Bureau of Labor Statistics (BLS), slips, trips and falls on the same level are the second leading cause of injury in the workplace. Falls on the same level are estimated by the BLS to cost, \$6.9 billion annually. Slips, trips and falls can occur in any business, but are of particular concern to businesses with considerable public and employee foot traffic – such as those in the retail, medical and service industries.

Slips, trips and falls may occur on level walking surfaces as well as on ramps and stairways. Major hazards associated with slip, trip and fall injuries are slippery surfaces, holes or broken surfaces, poor drainage or inadequate cleanup of spills or mud, ice, and water during inclement weather. Falls are frequently the result of both unsafe conditions and unsafe acts. Personal factors such as age, illness, emotional state, fatigue, inattention, and poor vision also contribute to falls.

Slippery surfaces can occur from: applying polymer over wax dressing; allowing inadequate drying time; buffing to a mirror-like gloss; incomplete removal of grease or oil; or allowing cleaning residue to mix with freshly applied finishes.

Materials used to prevent slips may become tripping hazards. These include mats with curled edges, tears or warps and abrupt changes in traction provided to adjacent walking surfaces. Mats that have become wet and dirty may make the soles of shoes wet and dirty rather than drying and cleaning them.

Floors

Floor surfaces and materials may contribute to slips and falls among employees and the general public. Proper choices in flooring materials, use of special finishes, mats, tapes, grooving, texturing and keeping the floor clean and dry can prevent slips and falls.

Evaluation

Major hazards are slippery surfaces, holes or broken surfaces, poor drainage or inadequate cleanup of spills or tracked in mud, ice and water during inclement weather. Identify and evaluate floor conditions during regular walk around surveys, and pay special attention to:

- Building entrances where water, mud, grit and dirt are tracked in
- Loading platforms that may be open to the elements
- Work areas around machinery or office equipment
- Areas where floor level changes due to steps or ramps

Any specific deficiencies observed should be discussed with management. Inquire into reasons for the deficiencies and review policies concerning floor maintenance, spill clean-up and actions during inclement weather.

A common cause of floor accidents is the slipping hazard of various types of floor surfaces. Terrazzo, marble, ceramic tile, painted wood or concrete, metal and some vinyl floors may be slippery unless non-slip measures are taken. Carpet is less slippery. Safety, appearance, initial cost, durability, and maintenance costs influence the selection of flooring type.

Regulations

OSHA General Industry Safety Standards, 1910.22 require floors to be clean and dry. Proposed regulations require floor surfaces to be free of recognized hazards and if the surface cannot be maintained free of hazards such as snow, ice or oil, there should be a means to minimize exposure. Consensus standard referenced by OSHA are ANSI A1264.2 2001 Standard for the Provision of Slip Resistance on Walking – Working Surfaces, and ASTM F 1637 – 95 Standard Practice for Safe Walking Surfaces. Regular inspection and maintenance should keep the surfaces in safe condition.

Slip, trip and fall accident control

Controls

Opportunities for improvement include:

- Increasing the slip resistance of slippery floor areas
- Replacing rotted, worn, loose and warped wood flooring
- Repairing cracks and holes in concrete floors
- Repairing tears in carpet
- Conducting regular and frequent housekeeping surveys
- Following flooring manufacturer's instructions
- Assigning maintenance and housekeeping personnel to specific designated areas
- Covering housekeeping principles and the need for clean up of spills in new employee orientation
- Establishing a procedure to clean only one section of floor at a time so traffic can pass safely

Increase the slip resistance of slippery floor areas. Contact floor covering suppliers and safety product distributors to determine the best material for the floor involved. Most suppliers can furnish a floor finish to specification, so specify a friction level when ordering. Comparative tests of various treatments may need to be made to determine which one is most preferable from all standpoints.

Rotted, worn, loose, and warped wood flooring should be repaired or replaced to reduce tripping hazards. Repair cracks and holes in concrete floors to reduce tripping hazards. Folded or wrinkled carpets should be stretched and tears should be repaired promptly.

Conduct regular and frequent housekeeping surveys to identify and correct unsafe floor conditions. Inspections also stimulate satisfactory housekeeping standards. Surveys should be documented. Follow flooring manufacturer's instructions to keep floors clean and safe. Use of the wrong cleaning materials, methods and surface finishing can cause suitable flooring types to deteriorate and become slippery. Floor maintenance and housekeeping procedures should be standardized and written. Assign maintenance and housekeeping personnel to specific designated areas to assure they perform their function effectively.

Cover housekeeping principles and the need for clean up of spills in new employee orientation. Procedures should include cleaning only one section of floor at a time so traffic can pass safely. Use "Wet Floor" warning signs, and rope off areas until floor cleaning is finished and the floor is dry. Post signs indicating alternate routes. Block doorways to stairs and escalators.

Aisles, walkways

Aisles should be wide enough to allow workers to move about freely while handling materials and allow safe passage of equipment. Aisles should be kept free of obstructions and have dry, slip-resistant surfaces.

Regulations

OSHA General Industry Safety Standards, 1910.22 require aisles to be clean and dry. Permanent aisles should be marked. Proposed standards would require 18 inch clearance around obstacles. National Fire Protection Association standards require access be kept clear to fire alarms and extinguishing equipment.

Controls

Opportunities for improvement may include:

- Increase aisle width.

Slip, trip and fall accident control

- Place mirrors, warning signs or signals.
- Mark aisles.
- Provide absorbent walk off mats.
- Assign supervisor responsibility for housekeeping.

Stairs and ramps

In the United States, stair accidents annually result in about 800,000 injuries requiring emergency room treatment. Approximately one person in seven will receive hospital treatment for a stair accident in his or her life. The Bureau of Labor Statistics estimates there are nearly 33,000 disabling work injuries a year involving falls to lower levels on stairs. This accident type accounts for 1.3% of all lost time injuries and illnesses. Eighty percent of the workers lost 18 days from work with an average hospital stay of seven days.

Recognition

Factors associated with high accident rates include:

- Riser/tread dimensions such that the stairs are steep
- Location of the stair between first and second floor, high use
- Dimensional irregularities, turns
- Low head room
- Edges difficult to orient
- Age of user
- Human error, distraction or inattention

A checklist for good stair features could be quite simple:

- Steps should be readily seen
- Treads are large enough to provide adequate footing
- Handrails are reachable and grasp able (Small children need to be considered in handrail height and grab bar spacing in residential, commercial and public buildings)
- Visual distractions in the vicinity of the stairs should be eliminated

Regulations

NFPA 101 Life Safety Code requires the following stair dimensions for new stairs:

Minimum clear width of stairs: 44 in, 36 in where less than 50 occupants use stairs

Height of risers:	4–8 inches
Minimum tread depth:	9–11 inches
Head room:	6' 8"
Maximum height between landings:	12 ft

Treads may have a maximum slope of 1/4 in per foot in order to shed water. The Life Safety Code requires handrails on each side of new stairs and ramps with a slope of 1:15 or greater. Intermediate handrails are required within 30 inches of all portions of the required stair width. A person can only reach about 24 inches to the side to grasp a handrail.

Slip, trip and fall accident control

The Life Safety Code, NFPA 101 requires guards on all surfaces that are 30" or more above the floor below to prevent falls over the open side. Such changes in elevation can occur at landings, balconies, corridors, passageways, floor or roof openings, ramps, aisles, porches or mezzanines. The code does not require guards on stairs with handrails on each side.

The NFPA 101 - Life Safety Code designates ramps as new or existing:

	New	Existing
Minimum width:	44 in	30 in
Maximum slope:	1 in 12	1 in 8
Maximum height between landings:	12 ft	12 ft

Ramps should have a slip resistant walking surface.

Proposed OSHA regulations require handrails on stairs over four risers and guardrails when fall distance is over four feet. OSHA allows riser height between 6.5 and 9.5 inches and minimum tread depth for closed risers of 8 in, 6 in for open risers.

Controls

Major opportunities for improvement may include:

- Make steps more apparent.
- Repair loose carpeting on treads.
- Turn guardrail and handrail ends into the wall.
- Install a handrail on the stair.
- Provide regular housekeeping inspections of stairs.

Steps can be made more apparent by using handrails, warning signs, marking the nosing of the steps or through illumination.

Repair loose carpeting on treads. Carpeting can be fastened by providing eyes and rods where treads and risers meet. Metal nosing can be installed flush with the tread material to provide a tactile clue at the step edge. Gritty, self adhesive tape can be applied to the stair tread and nosing but it requires regular maintenance.

Turn guardrail and handrail ends into the wall to prevent them from catching clothing. Install a handrail on the stair or ramp to help prevent serious falls. A good handrail should be:

- Circular, oval or oblong in cross section for a good grip; the use of rectangular handrails that do not allow a power grip is discouraged.
- Handrail circumference should be no less than 4.4 inches and no greater than 5.2 inches. For cylindrical handrails this translates to a diameter between 1.4 and 1.65 inches.
- Handrail height, measured from the top surface of the handrail to the tread surface at the leading edge of the tread should range from 31 to 33 inches, with 33 inches the preferred value whenever possible.
- Handrails should have a 4 5/8 inch finger clearance from any other object. A clearance of 2 1/4 inches is considered minimum.

Regular housekeeping inspections can help to keep stairs clear and dry.

Sidewalks

Include sidewalks in your inspection and preventative maintenance program. Check the condition of sidewalks as well as what type of material was used to construct them. Smooth materials such as marble and terrazzo should be avoided if possible. Rough finished concrete provides good slip resistance, even when wet.

Slip, trip and fall accident control

Evaluation

Sidewalks should be level, with no ridges or height changes greater than 1/4 to 1/2 inch. They should have serrations or a tactile change of surface at change of elevation. Sidewalks should have no holes large enough for a heel to fit into (not including spike heels). They should have a coefficient of friction greater than 0.5 when wet and have a non-slip textured surface finish.

Controls

Areas of risk improvement opportunity could include:

- Initiate a sidewalk maintenance program.
- Train maintenance or security personnel to inspect sidewalk conditions.
- Remove any worn or slippery sidewalk paint.
- Improve sidewalk drainage.
- Barricade sidewalk holes until repairs are completed.
- Install ramps or barricades over pipes or wires.
- Consider heated sidewalks if de-icing is difficult to maintain in high traffic areas.

Remove sidewalk paint or finish that may be worn or non-slip resistant. Smooth finished sidewalks can be very slippery when wet. Improve drainage to prevent the accumulation of standing water or ice on sidewalks. Ice and snow are major contributors to sidewalk slips and falls. Install a tactile change of surface if any visually impaired people use the sidewalk. This will assist them in determining changes in elevation such as steps and curbs.

Barricade off any holes or areas under repair to draw attention to them and prevent unauthorized access. Cover with a ramp or barricade, any pipes or wires laid across the sidewalk to prevent trips and falls. Consider heated sidewalks to prevent a buildup of ice and snow in high traffic walkways when it is difficult to keep up with adverse weather.

Train maintenance or security personnel to include sidewalk condition in their regular building checks. Initiate a sidewalk maintenance program which includes inspection of sidewalk conditions and prompt repair.

Lighting

General lighting of work areas and walkways may help prevent slips, trip and falls. General lighting includes natural sunlight, general overhead lighting and task lighting. Adequate lighting can help employees and the general public detect hazards and avert them.

Evaluation

Identify the areas where poor illumination or no illumination, as well as direct glare, reflected glare, dark shadows, and visual fatigue can contribute to accidents. These areas may include:

- Building entrances
- Parking lots
- Loading platforms and service entrances
- Work areas around machinery and office equipment
- Areas where floor level changes
- Stairs

Slip, trip and fall accident control

Controls

Opportunities for improvement include:

- Provide task lighting
- Reduce glare
- Missing or burned out light bulbs are indications of poor maintenance

Provide switches for stair lighting at each access to stairs so that lights can be turned on to reduce the risk of an employee climbing or descending a dark stair.

For more information, log in to the Risk Control Customer Portal at travelers.com/riskcontrol. (Need help? Read our [Registration Quick Guide](#).) You also can contact your Risk Control consultant or email Ask-Risk-Control@travelers.com.



travelers.com

The Travelers Indemnity Company and its property casualty affiliates. One Tower Square, Hartford, CT 06183

The information provided in this document is intended for use as a guideline and is not intended as, nor does it constitute, legal or professional advice. Travelers does not warrant that adherence to, or compliance with, any recommendations, best practices, checklists, or guidelines will result in a particular outcome. In no event will Travelers or any of its subsidiaries or affiliates be liable in tort or in contract to anyone who has access to or uses this information. Travelers does not warrant that the information in this document constitutes a complete and finite list of each and every item or procedure related to the topics or issues referenced herein. Furthermore, federal, state or local laws, regulations, standards or codes may change from time to time and the reader should always refer to the most current requirements. This material does not amend, or otherwise affect, the provisions or coverages of any insurance policy or bond issued by Travelers, nor is it a representation that coverage does or does not exist for any particular claim or loss under any such policy or bond. Coverage depends on the facts and circumstances involved in the claim or loss, all applicable policy or bond provisions, and any applicable law.

© 2008-2012 The Travelers Indemnity Company. All rights reserved. Travelers and the Travelers Umbrella logo are registered trademarks of The Travelers Indemnity Company in the U.S. and other countries. 644